DENDURANCE



OGIO[®] ENDURANCE Cadmium Jacket. OE502

front

back


LUX COTTON-RICH SOFTNESS LAY ERABLE WARMTH STRETCH FLATLOCK SEAMS FOR COMFORT REFLECTIVE DETAILS

- 4.3-ounce, 56/38/6 French terry cotton/poly/spandex
- Reflective OGIO Endurance heat transfer label for tag-free comfort
- 3-panel hood
- Zip-through collar with chin guard
- Metalux zipper with molded cord pull
- Set-in sleeves
- Reflective O heat transfer at right back shoulder
- Low er front pockets
- Reflective O Endurance heat transfer at left pocket
- 2x2 flat knit cuffs and hem

CARE INSTRUCTIONS

Machine w ash cold w ith like colors. Do not bleach. Tumble dry low. Warm iron if necessary

HOW TO MEASURE



CHEST WIDTH

Measure under the arm and around the fullest part of the chest with arms dow n, keeping tape horizontal.

SIZE CHART

	XS	S	М	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

COLOR INFORMATION

Please note: PMS code information is shown only when an exact match is available.



PMS NTR BLACK

